



Bounty Mining Limited

ACN: 107 411 067

**Suite 301, Level 3, 66 Hunter Street, Sydney NSW 2000, Australia
www.bounty.com.au**

23 October 2019

ASX Announcement

UPDATE ON ROOF FALL ANNOUNCEMENT

Bounty Mining Limited (**Bounty** or **Company**) (**ASX:B2Y**) confirms that on 22 October 2019 the CM13 continuous miner was successfully extracted from under the localised roof fall that occurred on 17 October 2019. CM13 is currently being inspected for any damage.

Bounty will provide a further update to the market once we have further details

For further information contact

Rob Stewart

Chairman

Bounty Mining Limited

Rob.stewart@bounty.com.au