



Bounty Mining Limited

ACN: 107 411 067

**Suite 301, Level 3, 66 Hunter Street, Sydney NSW 2000, Australia
www.bounty.com.au**

24 October 2019

ASX Announcement

RESUMPTION OF MINING

Bounty Mining Limited (Bounty or Company) (ASX: B2Y) confirms that production at Cook Colliery resumed on 24 October 2019. The CM02 continuous miner is operating in Panel 203B.

The CM13 continuous miner damaged in last week's roof fall is currently undergoing minor repairs and Bounty will provide an update when it is returned to service.

Bounty CEO, Jim Griffin, said, "It's good to be back in production. The Bounty team has worked hard to overcome this setback, and we continue to concentrate on safety as we learn from this incident and resume operations."

For further information contact

Rob Stewart

Chairman

Bounty Mining Limited

Rob.stewart@bounty.com.au